

## 2017 Fire Safety System

Hall Name	Fire Alarm Panel	Battery Back-Up	Monitor External Vendor	Monitor Internal	Smoke Detector	Heat Detector	Strobe Lights	Horn	Combination Devices	Illuminated Exit Signs	Fire Extinguisher	Fire Doors	Sprinkler System (water)	Evacuation Plans & Placards	Number of evacuation fire drills each calendar year
Aitchison Hall <a href="#">Simplex 4010</a>	Yes	Yes	No	No	102	5	33	103	0	12	15	14	No	*4	0
Cassat Hall <a href="#">Simplex 4010</a>	Yes	Yes	No	No	95	9	9	16	0	10	12	11	No	*4	0
Chlapaty Hall <a href="#">Simplex 4100 ES</a>	Yes	Yes	No	Yes	136	0	48	109	126	57	13	149	Yes	*4	0
Donnell Hall <a href="#">Simplex 4010</a>	Yes	Yes	No	No	95	9	9	16	0	10	12	11	No	*4	0
Park Village 2455 <a href="#">Simplex 4010</a>	Yes	No	No	No	63	4	6	8	0	9	5	26	*2	*4	0
Park Village 2465 <a href="#">Simplex 4010</a>	Yes	No	No	No	68	4	6	8	0	9	5	21	*2	*4	0
Park Village 2475 <a href="#">Simplex 4010</a>	Yes	No	No	No	68	4	6	8	0	9	5	21	*2	*4	0
Park Village 2525 <a href="#">Simplex 4004</a>	Yes	No	No	No	42	0	0	2	0	5	3	12	*2	*4	0
Park Village 2535 <a href="#">Simplex 4004</a>	Yes	No	No	No	42	0	0	2	0	5	3	12	*2	*4	0
Park Village 2545 <a href="#">Simplex 4004</a>	Yes	No	No	No	35	0	0	2	0	5	4	20	*2	*4	0
Seminary Village 67	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 69	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 71	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 73	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 91	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 93	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 95	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3
Seminary Village 97	No	No	No	No	5	0	0	0	0	0	0	1	No	*5	*3

\* 1 Building is only occupied while having chapel service.

\* 2 Full Sprinkler System is defined as having sprinklers in both the common areas & individual rooms.

\* 3 No evacuation fire drills are required.

\* 4 Evacuate to assembly/meeting location, no Evacuation Plans or Placards were posted.

\* 5 No evacuation drills were done (not required), no Evacuation Plans or Placards were posted.

Campus Housing	Fire Alarm Panel	Battery Back-Up	Monitor External Vendor	Monitor Internal	Smoke Detector	Heat Detector	Strobe Lights	Horn	Combination Devices	Illuminated Exit Signs	Fire Extinguisher	Fire Doors	Sprinkler System (water)	Evacuation Plans & Placards	Number of evacuation fire drills each calendar year
235 Algona Street	No	No	No	No	4	0	0	0	0	0	1	0	No	*5	*3
285 Algona Street	No	No	No	No	4	0	0	0	0	0	1	0	No	*5	*3
349 Algona Street	No	No	No	No	6	0	0	0	0	0	1	0	No	*5	*3
1896 Delhi Street	No	No	No	No	7	0	0	0	0	0	1	0	No	*5	*3
1360 Finley Street	No	No	No	No	3	0	0	0	0	0	1	0	No	*5	*3
2180 Grace Street	No	No	No	No	1	0	0	0	0	0	1	0	No	*5	*3
2141 Hale Street	No	No	No	No	5	0	0	0	0	0	1	0	No	*5	*3
2153 Hale Street	No	No	No	No	4	0	0	0	0	0	1	0	No	*5	*3
2170 Hale Street	No	No	No	No	5	0	0	0	0	0	1	0	No	*5	*3
2175 Hale Street	No	No	No	No	4	0	0	0	0	0	1	0	No	*5	*3
2180 Hale Street	No	No	No	No	3	0	0	0	0	0	1	0	No	*5	*3
2291 Lombard Street	No	No	No	No	6	0	0	0	0	0	1	0	No	*5	*3
2297 Lombard Street	No	No	No	No	4	0	0	0	0	0	2	0	No	*5	*3
2315 Lombard Street	No	No	No	No	5	0	0	0	0	0	1	0	No	*5	*3
2355 Lombard Street	No	No	No	No	6	0	0	0	0	0	1	0	No	*5	*3
877 McCormick Str.	No	No	No	No	3	0	0	0	0	0	1	0	No	*5	*3
959 McCormick Str.	No	No	No	No	7	0	0	0	0	0	1	0	No	*5	*3
1249 McCormick Str. (SGA House)	No	No	No	No	5	0	0	0	0	0	2	0	No	*5	*3
1085 McCormick Str.	No	No	No	No	5	0	0	0	0	0	1	0	No	*5	*3
1255 McCormick Str.	No	No	No	No	3	0	0	0	0	0	1	0	No	*5	*3
2305 Mineral Street	No	No	No	No	4	0	0	0	0	0	1	0	No	*5	*3
2356 Mineral Street	No	No	No	No	5	0	0	0	0	0	1	0	No	*5	*3
2386 West Street	No	No	No	No	4	0	0	0	0	0	1	0	No	*5	*3
2150 West 3 <sup>rd</sup> Street	No	No	No	No	5	0	0	0	0	0	1	0	No	*5	*3
55 Algona Street (Rental Property)	No	No	No	No		0	0	0	0	0		0	No	*5	*3
86 Collins Street (Rental Property)	No	No	No	No		0	0	0	0	0		0	No	*5	*3
68 Gandolfo Street (Rental Property)	No	No	No	No		0	0	0	0	0		0	No	*5	*3
1948 Grace Street (Rental Property)	No	No	No	No		0	0	0	0	0		0	No	*5	*3
Pulpit Rock (Rental Property)	No	No	No	No		0	0	0	0	0		0	No	*5	*3

\* 1 Building is only occupied while having chapel service.

\* 2 Full Sprinkler System is defined as having sprinklers in both the common areas & individual rooms.

\* 3 No evacuation fire drills are required.

\* 4 Evacuate to assembly/meeting location, no Evacuation Plans or Placards were posted.

\* 5 No evacuation drills were done (not required), no Evacuation Plans or Placards were posted.

Academic Buildings	Fire Alarm Panel	Battery Back-Up	Monitor External Vendor	Monitor Internal	Smoke Detector	Heat Detector	Strobe Lights	Horn	Combination Devices	Illuminated Exit Signs	Fire Extinguisher	Fire Doors	Sprinkler System (water)	Evacuation Plans & Placards	Number of evacuation fire drills each calendar year
Airport- Americas Hanger	No	No	No	No	2	0	0	0	0	5	9	3	No	N/A	0
Airport- Iowa Hanger	No	No	No	No	0	0	0	0	0	4	5	0	No	N/A	0
Airport- Operations Center	No	No	No	No	3	0	0	0	0	4	5	9	No	N/A	0
Alumni Hall	No	No	No	No	0	0	0	0	0	1	2	0	No	N/A	*1
Blades Hall <a href="#">Simplex 4010 ES</a>	Yes	Yes	No	No	3	3	7	0	18	9	6	28	No	N/A	0
Cedar Rapids Campus <a href="#">Simplex 4010</a>	Yes	Yes	Yes	No	21	0	9	0	4	6	2	0	No	N/A	0
Chlapaty Wellness Center <a href="#">Simplex 4100 U</a>	Yes	Yes	No	No	43	1	19	2	61	17	23	3	Yes	N/A	0
Daycare Center	No	No	No	No	8	0	0	3	0	3	4	1	No	N/A	0
Dunlap Technology Center <a href="#">Simplex 4004</a>	Yes	Yes	No	No	16	0	0	0	9	14	10	42	Yes	N/A	0
Goldthorp Science Center <a href="#">Simplex 4100 U</a>	Yes	Yes	No	No	62	1	0	0	60	20	14	10	Yes	N/A	0
Heating Plant	No	No	No	No	0	0	0	0	0	1	4	5	No	N/A	*1
Heritage Center <a href="#">Simplex 4100 ES</a>	Yes	Yes	No	No	100	10	29	0	73	49	13	39	Yes	N/A	0
Hub- Computer Technology Center <a href="#">Simplex 4020</a>	Yes	Yes	No	No	3	0	2	0	1	2	2	2	No	N/A	0
Maintenance Building	No	No	No	No	0	0	0	0	0	5	9	0	No	N/A	0
Maintenance Fuel Shed	No	No	No	No	0	0	0	0	0	0	1	0	No	N/A	N/A
McCormick/ Stoltz Gym <a href="#">Simplex 4100 U</a>	Yes	Yes	No	No	24	6	3	3	35	38	21	40	Yes	N/A	0
Mercer Birmingham Hall <a href="#">Simplex 4010</a>	Yes	Yes	No	No	18	1	0	0	24	8	6	0	No	N/A	0

Myers Building (MTAC) <a href="#">Simplex 4010</a>	Yes	Yes	No	No	54	10	0	0	43	23	15	15	Yes	N/A	0
Myers Library <a href="#">Simplex 4020</a>	Yes	Yes	No	No	64	20	0	0	44	27	18	25	Yes	N/A	0
Peters Commons <a href="#">Simplex 4010 ES</a>	Yes	Yes	No	No	2	1	8	0	37	15	13	17	No	N/A	0
Severance Hall <a href="#">Simplex 2001 (1980)</a>	Yes	Yes	No	No	19	0	0	0	10	17	14	11	No	N/A	0
Smith Hall	No	No	No	No	0	0	0	3	0	6	7	0	No	N/A	0
Soccer Press Box	No	No	No	No	0	0	0	0	0	0	2	0	No	N/A	0
Van Vliet Hall <a href="#">Faraday</a>	Yes	Yes	No	No	0	0	0	3	0	8	4	3	No	N/A	0
Veteran's Memorial Training Center <a href="#">Simplex 4010 ES</a>	Yes	Yes	No	No	2	0	4	0	23	3	7	2	Yes	N/A	0
Visitor's Bleachers <a href="#">Simplex 4006</a>	Yes	Yes	No	No	0	0	2	0	9	2	3	0	No	N/A	N/A
Visitor's Snack Bar	No	No	No	No	3	2	0	0	2	0	1	0	No	N/A	N/A

\* 1 Building is only occupied while having chapel service.

\* 3 No evacuation fire drills are required.

\* 5 No evacuation drills were done (not required), no Evacuation Plans or Placards were posted.

\* 2 Full Sprinkler System is defined as having sprinklers in both the common areas & individual rooms.

\* 4 Evacuate to assembly/meeting location, no Evacuation Plans or Placards were posted.